

Administrative Office
 3901 Commerce Park Drive
 Raleigh, NC 27610
 Sales/Service: (855) 324-3085
 Dealer: (855) 879-8093



Shipping/Mfg. Location
 4654 East Markle Road
 Markle, IN 46770
 Technical: (877) 291-6309

MAX RATE CHART

| Task | Hours | Price |
|--------------------------------------|-------|-------|
| Replace Control Board | 3 | \$240 |
| Replace E-Chain | 1 | \$80 |
| Replace Reed Switches | 1 | \$80 |
| Replace Reed Switch Target | .5 | \$40 |
| Replace 40 AMP Relays | 2 | \$160 |
| Replace Mechanical Limit Switch | .25 | \$80 |
| Service Door Magnet | 2 | \$160 |
| Service Door Light | 1 | \$80 |
| Service Under Truck Light | 1 | \$80 |
| Service Air Bag Shunt (Resistor) | 3 | \$240 |
| Service Door Ajar Switch | 1 | \$80 |
| Replace 16 AMP Push Button Breaker | 0.5 | \$40 |
| Service Tilt Switch | 1 | \$80 |
| Scan Tool - C Reader Professional | 0.5 | \$40 |
| Service Power Unit w/ Pump | 2 | \$160 |
| Service Pump Solenoid | .5 | \$40 |
| Service Manifold Assembly Delta | 4 | \$320 |
| Service Velocity Fuse (Door or Lift) | .5 | \$40 |
| Replace Hose | 1 | \$80 |
| Troubleshoot Airbag Light | 3 | \$240 |
| Replace Swing Arm Pin | 2 | \$160 |
| Replace Cylinder | 1 | \$80 |
| Replace Seat Belt Roller | 1 | \$80 |
| Adjust Door | 1 | \$80 |
| Adjust Pump Pressure | .5 | \$40 |

* Rates and times as of 3/12/17 and are subject to change.

** Contact ATC Service department and a GM dealer when unable to diagnose the problem in time.